


D=Hole diameter  
1/2" to 1"




Repair procedure for 1/2" to 1" exploratory holes.

1. Remove material from hole using compressed air in the presence of City Inspector.
2. Rod in Quikrete 8620—Concrete Repair or approved equal.
3. 3M Loop Detector Sealant 5000 or Quikrete 8630—Asphalt Repair to finish grade.

**CITY OF SAN LEANDRO**

NO.	REVISIONS	DATE	BY

**1/2" TO 1" EXPLORATORY HOLE  
REPAIR REQUIREMENTS**

APPROVED  
  
 Kenneth Joseph, City Engineer R.C.E. No.34870  
 Expires 9/30/13

DRAWN	AMS	CHECKED	KJ/KRC	DATE	Aug 2012	SCALE	NONE	SHEET	1 OF 1	DWG.	146	CASE	3101
-------	-----	---------	--------	------	----------	-------	------	-------	--------	------	-----	------	------